

Rome Ancient Walls Satellite Monitoring Project



MARINA MARCELLI
Roma Capitale
Sovrintendenza ai Beni Culturali
marina.marcelli@comune.roma.it

DANIELE SPIZZICHINO - GABRIELE LEONI
ISPRA-Dipartimento per il Servizio Geologico d'Italia
daniele.spizzichino@isprambiente.it
gabriele.leoni@isprambiente.it




ROMA

Sovrintendenza Capitolina ai Beni Culturali

MISSION AND ACTIVITIES

Management, conservation and enhancement
of all historical, artistic, and archaeological
properties of the Municipality of Rome



MUSEUMS - MONUMENTS

ancient, medieval
modern, contemporary




THE UNESCO SITE OF ROME AND THE AURELIAN WALL



The ancient circuit, with 18 main gates and 383 towers, ran for 19 km surrounding an area of 13.7 Km²



"The Historic Centre of Rome, the extraterritorial properties of the Holy See in that City enjoying Extraterritorial Rights and S. Paolo fuori le Mura".



1.469,17 hectares
1.430,8 of the Italian side
38,9 of the Vatican State

CONSERVATION AND MANAGEMENT OF URBAN ARCHAEOLOGICAL HERITAGE

Critical elements

Environmental factors (Pollution, Climate/micro-climate, Vegetation and chemical/biological agents, Earthquakes, Water damage, Geological substrate)


Anthropic factors (Phases and construction techniques, Demolition and cutting for urban expansion, Ancient and modern conservative interventions, Superstructures, Vandalism)





Collapse (2007) and restoration



«Progetto Osservatori» G.I.S. A Risk Map of the Walls





in red: high risk!









399 WHL Sites



Property RISK INDEX



7 Case Studies



THE ROME WALLS CASE STUDY

from *Progetto Osservatori* Report ...

SETTORE K		Via delle Mura Latine (da K01 a K13)	SCHEDA 10
Localizzazione	Fronte esterno	Via delle Mura Latine da Porta Latina a porta S. Sebastiano	
	Fronte interno	Via di Porta S. Sebastiano	
Accessibilità	Fronte esterno	accessibile	Frazioni di rispetto al interno della proprietà privata
	Fronte interno	accessibile	Rappresentazione del livello presso la FAO Ambasciata del Canada presso la S. Sede Proprietà Barbara S.r.l.
Praticabilità	Camminamento	Percorribile in parte da K01 a K08 non in sequenza	
		percorribile	verso il Museo delle Mura da K08 a K13
Uso attuale	Camminamento	non utilizzato	Torre K13 - Depositi/magazzini del Museo
	Interiori torri	non utilizzati	
Opre provvisoriali	Fronte esterno	Resinzione provvisoria per periodo	
Area a verde	Fronte esterno	degradata	nelle aree non indicate nella proprietà privata
Criticità	Fronte esterno	Sicurezza	Conservativa
	Fronte interno	Sicurezza	Conservativa
	Camminamento	Sicurezza	Conservativa
Dati dimensionali medi	Fronte esterno	lunghezza m 450	Fronte interno m 11
		h m 11	
Stima dei costi ... al netto dell'IVA			
Lavori		€ 3.700.000,00	
Costi per la sicurezza		€ 350.000,00	
Somme a disposizione per opere in economia - JPE - Rimborso a fattura		€ 450.000,00	
TOTALE GENERALE		€ 4.500.000,00	
Stima dei tempi		750 gg	


Attributes:

- Date
- **Typology**
- Dimensions
- Causes
- Wall element
- Intervention
- Responsible




Dati dimensionali medi	
Fronte esterno	lunghezza m 450
Fronte interno	h m 11
	m 11
Stima dei costi ... al netto dell'IVA	
Lavori	€ 3.700.000,00
Costi per la sicurezza	€ 350.000,00
Somme a disposizione per opere in economia - JPE - Rimborso a fattura	€ 450.000,00
TOTALE GENERALE	€ 4.500.000,00
Stima dei tempi	750 gg

... to Damage Inventory




Rupture Typology:

▲ damage	7
▲ debris fall	3
▲ detachment	16
▲ fall	2
▲ instability	3
▲ slide	1



PanGeo

ISPRRA
Istituto Superiore per la Protezione e la Ricerca Ambientale





PS INSAR MONITORING


CSK 2011–2014



Wall cover detachment due to train transit on the railway.
Restored in 2012.




ID 22	# of PS	Vel.	STD	Coherence
50m buffer	66	-3.60	0.27	0.78
614A1008nR2	1	-11.04	0.40	0.73



THE ROME WALLS RESULTS

Count of damages by displacement and timing compared to PS dataset timespan (2011-2014)



Ground Displacement		Rupture period						
style	mm/yr	pre	in	post	along	susceptible	none	
uplift	> 3	1						1
weak uplift	2 ÷ 3							
stable	-2 ÷ 2	2		1	3	2		1
weak lowering	-2 ÷ -3		2		1	1		1
lowering	< -3		2		2			6

- ➔ DInSAR analysis provide a large number of site-wide displacement measurements (PS) with small cost and without impact.
- ➔ PS are proxy data useful to define warning thresholds and to build site scale early-warning systems.
- ➔ Ongoing and future high resolution monitoring allows stakeholders to properly plan interventions, as restoring and mitigation.
- ➔ The good results foster the improvement of multidisciplinary approach.

Thank You!



<http://www.sovraintendenzaroma.it/content/progetto-osservatori-un-gis-il-monitoraggio-dei-monumenti-di-roma>

<http://www.prothego.eu/>

